

Big Flats Elementary School - Water Testing Summer 2021

Sample Identification	Description	Initial Results	Results After Remediation
300F	Classroom	5.7	
301F	Classroom	2.2	
302F	Classroom	5.5	
304F	Classroom	4.1	
305F	Classroom	3.9	
306F	Classroom	6.3	
308F	Classroom	4.6	
310F	Classroom	5.4	
311F	Classroom	5.0	
312F	Classroom	5.3	
313F	Classroom	2.1	
315F	Classroom	4.2	
FACL4	Men's Lav near 307	8.2	
FACL5	Women's Lav near 307	4.6	
FACL3	Lav near Library	4.5	
BOT3	Bottle Filler by Library	<1.0	
BOT2	Bottle Filler by Gym	<1.0	
BOT1	Bottle Filler - Cafeteria	<1.0	
KIT4	Kitchen	9.9	
KIT3	Kitchen	4.2	
KIT2	Kitchen	1.5	
KIT1	Kitchen	2.9	
FACR1	Faculty Room in music	5.7	
PE1	PE Office	9.8	
NUR1	Nurses Office Sink	3.7	
NUR2	Nurses Office Sink	8.5	
NUR L	Nurses Office Lav	3.0	
CON F	Conference Room by Nurses Office	10.5	
MAIL	Mailroom	2.7	
100F	Classroom	3.7	
101F	Classroom	5.5	
102F	Classroom	<1.0	
103F	Classroom	2.5	
104F	Classroom	4.6	
105F	Classroom	67.3	4.5, <1
BOT4	Bottle Filler by Nurses Office	<1.0	
FACL1	Faculty Lav by Nurses Office	2.3	
FACL2	Faculty Lav by PTO Office	1.3	
ARTA	Art Room	7.8	
ARTB	Art Room	4.7	
ARTC	Art Room	4.0	
MOL1	Lav by Main Office	2.7	
FACML	Mens Lav by Music Wing	3.7	
FACWL	Women's Lav by Music Wing	8.4	

203F	Classroom	2.8	
204F	Classroom	3.6	
205F	Classroom	5.9	
206F	Classroom	4.2	
207F	Classroom	6.8	
208F	Classroom	4.3	
209F	Classroom	4.3	
210F	Classroom	7.1	
211F	Classroom	12.4	

NYSDOH Action Level for Lead of 15 ppb