

Horseheads Intermediate School - Water Testing Summer 2021

Sample Identification	Description	Initial Results
405 F	Classroom	7.1
407 F	Classroom	1.3
407 L	Classroom	1.9
409 F	Classroom	2.6
409 L	Classroom	3.2
411 F	Classroom	1.0
411 L	Classroom	1.3
413 F	Classroom	<1.0
413 L	Classroom	<1.0
415 F	Classroom	<1.0
415 L	Classroom	4.0
417 F	Classroom	1.6
417 L	Classroom	2.6
BOT 1	Bottle Filler by Rear Stage Door	<1.0
PE-1	PE Office (IS side)	6.8
327 - F	Classroom	6.8
325 - F	Classroom	2.9
330-F	Classroom	3.4
323-F	Classroom	4.5
321-F	Classroom	5.5
332-F	Classroom	16.6
326-F	Classroom	1.8
319-F	Classroom	4.4
317-F	Classroom	6.0
324F	Classroom	3.0
322F	Classroom	6.1
FAC CON 1	Faculty/Conference Room	36.4
320 F	Classroom	3.6
318F	Classroom	3.8
316F	Classroom	4.7
314F	Classroom	9.8
315A	Classroom	40.5
315B	Classroom	3.4
313A	Classroom	1.2
313B	Classroom	<1.0
312F	Classroom	19.2
310F	Classroom	3.7
FACCON 2	Faculty Room, across from 310	<1.0
308F	Classroom	14.6
306F	Classroom	5.7
304F	Classroom	6.7
302F	Classroom	5.2
311F	Classroom	6.9

309F	Classroom	3.4
300F	Classroom	8.0
NUR1	Nurse's Office	2.3
NUR2	Nurse's Office	5.1
307F	Classroom	3.7
305F	Classroom	4.0
303F	Classroom	6.6
301F	Classroom	8.1
MO-1	Main Office	3.5
MOL-1	Main Office Lav	3.5
LIB-1	Library	9.9
BOT-2	Bottle Filler, 400 Wing	<1.0
BOT-3	Bottle Filler, across from Library	<1.0

NYSDOH Action Level for Lead of 15 ppb