

Horseheads High School - Water Testing Summer 2021

Sample Identification	Description	Initial Results
KIT-1	Kitchen	1.1
KIT-2	Kitchen	1.0
SP1	Kitchen (steam pot)	2.3
KIT 3	Kitchen	1.2
KIT 4	Kitchen	<1.0
KIT 5	Kitchen	1.3
KIT 6	Kitchen	<1.0
KIT 7	Kitchen	<1.0
KIT 8	Kitchen	<1.0
KIT 9	Kitchen	<1.0
BOT-1	Bottle Filler	<1.0
BOT-2	Bottle Filler	<1.0
BOT-3	Bottle Filler	<1.0
BOT-4	Bottle Filler	<1.0
BOT-5	Bottle Filler	5.7
<b>BRF</b>	<b>Band Room</b>	<b>16.7</b>
WDR	Womens Dressing Room	<1.0
MDR	Mens Dressing Room	1.1
GPE	Girls PE Coach Lav	2.1
GLR-1	Girls Locker Room	<1.0
GLR-2	Girls Locker Room	<1.0
BPE	Boys PE Coach Lave	6.8
BLR-1	Boys Locker Room	1.4
BLR-2	Boys Locker Room	2.4
PSY	Psychologist Office	11.9
REGL	Registrar - Lav	6.6
REGF	Registrar - sink	3.7
FAC3W	Women's Restroom -by Guid	7.4
FAC3M	Men's Restroom-by Guid	5.6
GUI	Guidance Office	3.2
MFT	Maintenance Office Fountain	<1.0
MF-1	Maintenance Shop	3.4
MF-2	Maintenance Shop	6.0
<b>MF-3</b>	<b>Maintenance Office - Lav</b>	<b>22.1</b>
MF-4	Maintenance Office - Lav	8.7
<b>204-1</b>	<b>Classroom</b>	<b>19.5</b>
204-2	Classroom	2.2
100A-1	Classroom - 1st Draw	6.8
100A-2	Classroom - 2nd Draw	1.0
101A-1	Classroom - 1st Draw	3.8
101A-2	Classroom - 2nd Draw	<1.0
<b>102A-1</b>	<b>Science Prep Room - 1st Draw</b>	<b>42.0</b>
102A-2	Science Prep Room - 2nd Draw	1.4

ICE-1	Ice Machine - Kitchen	<1.0
GLAV3A	Girls Lav -- 2nd floor by 256	28.6
GLAV3B	Girls Lav - 2nd floor by 256	4.8
GLAV3C	Girls Lav - 2nd floor by 256	4.0
GLAV3D	Girls Lav - 2nd floor by 256	14.5
TL-2	2nd Floor Faculty Room	8.9
FAC 3M	Men's Faculty Room -by 243	7.0
FAC 3W	Womens's Faculty Room - by 243	16.5
BLAV 4A	Boy's Lav -by 270	23.2
BLAV 4B	Boy's Lav -by 270	15.2
BLAV 4C	Boy's Lav -by 270	9.9
GLAV 4A	Girls Lav - by 270	5.7
GLAV 4B	Girls Lav -by 270	5.1
GLAV 4C	Girls Lav - by 270	4.4
LIBF	Library	<1.0
BOT-1	Bottle Filler by South Gym	<1.0
BOT-2	Bottle Filler in Science Corridor	<1.0
BOT-3	Bottle Filler in Science Corridor	<1.0
BOT-4	Bottle Filler in Library Corridor	<1.0
BOT-5	Bottle Filler in Library Corridor	<1.0
N1	Nurses Office	2.2
N2	Nurses Office	12.5
NLAV	Nurses Office - Lav	1.6
SPTLUH	Old Supt Conf Room	5.7
SPTLAV	Ath. Office Lav	8.5
SML-1	Mens Lav - Across from South Gym	2.1
SWL-1	Women's Lav across from S. Gym	<1.0
EDU-1	Asst. Supt Office	15.7
EDU-2	Asst. Supt Office	13.2
EDU-3	Asst. Supt Office	5.1
SML-2	Mens Lav - Across from Stud. Serv	<1.0
SWL-2	Women's Lav across from Stud. Serv	<1.0
SWL-3	Women's Lav across from Stud. Serv	<1.0
SS-1	Student Services - Sink	2.4
301-1	Classroom	1.5
301-2	Classroom	1.3
FAC-1	Faculty Room by South Boiler Room	2.0
EDS-1	Curriculum Center	<1.0
EDS-M	Curriculum Center - Men's Lav	<1.0
EDS-W	Curriculum Center - Women's Lav	1.3
154F	Classroom	15.8
152F	Classroom	7.8
150F	Classroom	7.4
151A	Classroom	3.3
151B	Classroom	2.6
FAC 2A	Faculty Lav by 151	27.1
FAC 2B	Faculty Lav by 151	9.6

FAC 2C	Faculty Lav by 151	6.1
FAC 2D	Faculty Lav by 151	6.5
153 F	Classroom	4.2
155A	Classroom	6.4
155B	Classroom	9.4
157A	Classroom	1.1
157B	Classroom	1.3
GLRF	South Wing Girls Locker Room	14.4
GPE	South Girls PE Coach Lav	8.0
BLRF	South Wing Boys Locker Room	6.9
BPE	South Boys PE Coach Lav	19.1
BLAV3A	Boys Lav by 256	12.8
BLAV3B	Boys Lav by 256	54.7
BLAV3C	Boys Lav by 256	28.1
BLAV3D	Boys Lav by 256	32.6
161A	Classroom	1.4
163A	Classroom	3.3
247A	Classroom	2.2
253B	Classroom	2.8
255A	Classroom	3.4

**NYSDOH Action Level for Lead of 15 ppb**

All devices that are above the NYSDOH action level are currently posted as non-potable water or have been taken out of service. Parts are ordered but delayed due to Covid 19