

Horseheads Middle School - Water Testing, Summer 2021

Sample Identification	Description	Initial Results
KIT-1	Kitchen	1.4
KIT-2	Kitchen	<1.0
KIT-3	Kitchen	5.0
BLR-1	Boys Locker Room	8.7
BLR-2	Boys Locker Room	7.5
BPE	Coaches Office - Boys Locker Room	16.9
GRL1	Girls Locker Room	7.9
GRL2	Girls Locker Room	8.1
GPE	Coaches Office - Girls Locker Room	10.1
BOT-1	Bottle Filler across from LGI	<1.0
MOF	Main Office Break Room	1.6
MOLM	Main Office Lav (Left)	2.3
MOL-W	Main Office Lav (Right)	1.4
NUR-1	Nurses Office	3.1
NUR-2	Nurses Office	3.6
HCL-1	Lav next to Language Office	9.6
221F	Classroom	4.9
FACF2	Copy Room by Room 221	3.7
BOT-2	Bottle Filler by Room 217	<1.0
214-F	Classroom	2.3
216-A	Classroom	3.0
216-B	Classroom	2.2
216-C	Classroom	1.9
216-D	Classroom	2.5
216E	Classroom	2.3
216F	Classroom	2.0
227F	Classroom	6.6
FAC-1	Main Faculty Room	1.2
199F	Classroom	1.3
101F	Classroom	3.3
106AF	Classroom	3.6
BOT-3	Bottle Filler by Room 199	<1.0
BOT-M	Bottle Filler by Room Main Office	<1.0
BOT-A	Bottle Filler by Art Rooms	2.8
BOT-B	Bottle Filler by Tech Rooms	<1.0
CONC1	Concession Stand	<1.0
CONC2	Concession Stand	1.3

NYSDOH Action Level for Lead of 15 ppb

All devices that are above the NYSDOH action level are currently posted as non-potable water or have been taken out of service. Parts are ordered but delayed due to Covid 19